



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining


MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

### Minerals Regulatory Program

### June 14, 2012

Reviewed: 

<b>Mine Name:</b> Leamington Cement Plant	<b>Permit Number:</b> M/023/0004
<b>Operator Name:</b> Ash Grove Cement Company	<b>Inspection Date:</b> June 13, 2012
<b>Inspector(s):</b> Josh Nelson, Gordon Jarrett	<b>Time:</b> 9:00 – 10:20 AM
<b>Other Participants:</b> none	<b>Mine Status:</b> Active
<b>Weather Condition:</b> clear sky 80's	<b>Last Inspection:</b> July 20, 2011
<b>Bond Renewal Date:</b> 07/22/2012	<b>Bond Amount:</b> \$4,536,300
<b>Surface Ownership:</b> Fee	<b>Mineral Ownership:</b> Fee
<b>Last Year of Production:</b> 794,592 tons	<b>Acreage:</b> 273 acres

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/>
2. Bond/Bond Release	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Annual Fees	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/>
4. Annual Report	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/>
5. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

### Purpose of Inspection:

This was a routine inspection.

### Inspection Summary:

- The bond is due for escalation in July 2012. The Permittee was informed of the escalation and they will provide the updated reclamation cost estimates.
- Annual fee and report are up to date.
- The site is secure and signs have been place to warn the public of hazards.
- The roads are maintained.

The Permittee is ~~know~~ storing and processing sandstone from their Neilson Pit at the Leamington Quarry.

**Conclusions and Recommendations:**

The bond needs to be escalated.

**Directions to Site:**

The site is approximately 5 miles north of Leamington, Utah on highway 132. One can see the plant from the road.

**Inspector's Signature**  \_\_\_\_\_  
WHW:  
cc: (OPERATOR)

O:\M023-Juab\M0230004-Leamington\Inspections\INSP061320121.doc



Sandstone pile that will be processed on site.



Active pit



Active pit and roads